

# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 3

Sewershed : Gwynn Falls

Company : URS

Date : 07/20/2009

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry : X Damp :    Wet :   


Supervisor : Ryan Lamont

Manhole ID : S08I\_009MH

Test ID : S1032-007004

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



## LEGEND

- SMOKE OBSERVATION
- BLOWER LOCATIONS
- MANHOLE
- SEWER LINE
- SMOKE RUN

Defect Code	Defect Description
SL	Service Lateral
TJ	Transition Joint
DD	Driveway Drain
WWD	Window Well Drain
STRD	Stairwell Drain
AD	Area Drain
DS	Downspout
DSC	Downspout Connection
FD	Foundation Drain

Defect Code	Defect Description
CB	Catch Basin
SD	Storm Ditch
SWMH	Storm Manhole
MAIN	Main Sewer
SANMH	Sewer Manhole
CO	Cleanout
OTHER	Other
IOB	Inside of Building

# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 2 of 3

Sewershed : Gwynn Falls

Company : URS

Date : 07/20/2009

Test to be Performed :  
Smoke : X Dyed Water :   

Ground Condition :  
Dry : X Damp :    Wet :   

Supervisor : Ryan Lamont

Manhole ID : S081 009MH

Test ID : S1032-007004

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID

7/20/09 08.0  
URS

BALTIMORE CITY  
PROJECT NO. 1032  
GWYNNS FALLS SEWERSHED STUDY  
SMOKE TEST OBSERVATION FORM

1032-007004-001

ADDRESS: 5302 Wendley Rd. /  
Kingston Rd.

DEFECT: Catch Basin

Location: N/A; Type: Catch Basin; Smoke:  
Light; Status: Public ROW

Landscape



Defect



ID

7/20/09 08.0  
URS

BALTIMORE CITY  
PROJECT NO. 1032  
GWYNNS FALLS SEWERSHED STUDY  
SMOKE TEST OBSERVATION FORM

1032-007004-002

ADDRESS: 501 Kingston Rd.

DEFECT: Service Lateral

Location: N/A; Type: Service Lateral; Smoke:  
Heavy; Status: Private Property

Landscape



Defect





# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 3 of 3

Sewershed : Gwynn Falls

Company : URS

Date : 07/20/2009

Test to be Performed :  
Smoke : X Dyed Water : \_\_

Ground Condition :  
Dry : X Damp : \_\_ Wet : \_\_

Supervisor : Ryan Lamont


Manhole ID : S08I 009MH

Test ID : S1032-007004

Notifications (Residents, Fire, 311) :  
Yes

**Field Sketch :** (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property


Landscape



Defect



ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property

Landscape



Defect

